



Cheyney State University of Pennsylvania
Cheyney University Police Department – Fire Safety Division

ACADEMIC/ADMISTRATIVE BUILDING FIRE EXTINGUISHER REPORT

Building: ADA GEORGE DINING HALL

Date/Time of Inspection: February 4, 2013

Date/Time of Inspection: Fire Extinguisher Number	Date of Last Inspection	Comments
#1 at entrance	missing	missing
#7 near freezer	1-4-13	OK
#11 near 205	1-4-13	OK
#8 kitchen/sink	1-4-13	OK
#7 loc 12 exit in kit	1-4-13	OK
#5 near elevator	1-4-13	OK
#6 loc 14	1-4-13	OK
#9 in kitchen	1-4-13	OK
1-1 lower level exit	1-4-13	OK
1-2	1-4-13	OK
1-3 at stairwell	1-4-13	OK
1-5 in stairwell	1-4-13	OK
loc #6 in basement	1-4-13	OK
loc #3 basement	1-4-13	OK
1-1 near roll up door	1-4-13	OK
1-2 in storeroom	moved	moved
1-3 inside dance hall	1-4-13	OK
1-4 in stairwell	1-4-13	OK
Loc 16 " dance hall	1-4-13	Ok
Loc 17 in stairwell	1-4-13	OK
Loc 14 dining area	1-4-13	OK
Loc 13 stairwell	1-4-13	OK

P/O Richardson

Valores Richardson

Fire Compliance Officer/Asst Patrol Officer

J.D. Richards

Chief of Police

2-4-13

Date

2-28-13

Date



Cheyney State University of Pennsylvania
Cheyney University Police Department – Fire Safety Division

ACADEMIC/ADMISTRATIVE BUILDING FIRE EXTINGUISHER REPORT

Building: ADA GEORGE DINING HALL

Date/Time of Inspection: March 4, 2013 0900hrs

Date/Time of Inspection: Fire Extinguisher Number	Date of Last Inspection	Comments
#1 at entrance	missing	missing
#7 near freezer	2-4-13	OK
#11 near 205	2-4-13	OK
#8 kitchen/sink	2-4-13	OK
#7 loc 12 exit in kit	2-4-13	OK
#5 near elevator	2-4-13	OK
#6 loc 14	2-4-13	OK
#9 in kitchen	2-4-13	OK
1-1 lower level exit	2-4-13	Recharge
1-2	2-4-13	OK
1-3 at stairwell	2-4-13	OK
1-5 in stairwell	2-4-13	Recharge
loc #6 in basement	2-4-13	OK
loc #3 basement	2-4-13	OK
1-1 near roll up door	1-4-13	OK
1-2 in storeroom	moved	moved
1-3 inside dance hall	2-4-13	OK
1-4 in stairwell	2-4-13	OK
Loc 16 " dance hall	2-4-13	Ok
Loc 17 in stairwell	2-4-13	OK
Loc 14 dining area	2-4-13	OK
Loc 13 stairwell	2-4-13	OK

P/O Richardson, P/O Miles

Dalores Richardson
Fire Compliance Officer/Asst Patrol Officer

3.4.13
Date

Lawrence W. Richards
Chief of Police

Date



Cheyney State University of Pennsylvania
Cheyney University Police Department – Fire Safety Division


ACADEMIC/ADMISTRATIVE BUILDING FIRE EXTINGUISHER REPORT

Building: ADA GEORGE DINING HALL


Date/Time of Inspection: April 17, 2013 0930hrs

Date/Time of Inspection: Fire Extinguisher Number	Date of Last Inspection	Comments
#1 at entrance	missing	missing
#7 near freezer	3-4-13	OK
#11 near 205	3-4-13	OK
#8 kitchen/sink	3-4-13	OK
#7 loc 12 exit in kit	3-4-13	OK
#5 near elevator	3-4-13	OK
#6 loc 14	3-4-13	OK
#9 in kitchen	3-4-13	OK
1-1 lower level exit	3-4-13	Recharge
1-2	3-4-13	OK
1-3 at stairwell	3-4-13	OK
1-5 in stairwell	3-4-13	Recharge
loc #6 in basement	3-4-13	OK
loc #3 basement	3-4-13	OK
1-1 near roll up door	3-4-13	OK
1-2 in storeroom	moved	moved
1-3 inside dance hall	3-4-13	OK
1-4 in stairwell	3-4-13	OK
Loc 16 " dance hall	3-4-13	Ok
Loc 17 in stairwell	3-4-13	OK
Loc 14 dining area	3-4-13	OK
Loc 13 stairwell	3-4-13	OK

P/O Richardson, P/O Miles


Fire Compliance Officer/Asst Patrol Officer

4.17.13
Date


Chief of Police

Date



Cheyney State University of Pennsylvania
Cheyney University Police Department – Fire Safety Division

ACADEMIC/ADMISTRATIVE BUILDING FIRE EXTINGUISHER REPORT

Building: ADA GEORGE DINING HALL

Date/Time of Inspection: May 6, 2013 1030hrs

Date/Time of Inspection: Fire Extinguisher Number	Date of Last Inspection	Comments
#1 at entrance	missing	missing
#7 near freezer	4-17-13	OK
#11 near 205	4-17-13	OK
#8 kitchen/sink	4-17-13	OK
#7 loc 12 exit in kit	4-17-13	OK
#5 near elevator	4-17-13	OK
#6 loc 14	4-17-13	OK
#9 in kitchen	4-17-13	OK
1-1 lower level exit	4-17-13	Recharge
1-2	4-17-13	OK
1-3 at stairwell	4-17-13	OK
1-5 in stairwell	4-17-13	Recharge
loc #6 in basement	4-17-13	OK
loc #3 basement	4-17-13	OK
1-1 near roll up door	4-17-13	OK
1-2 in storeroom	moved	moved
1-3 inside dance hall	4-17-13	OK
1-4 in stairwell	4-17-13	OK
Loc 16 " dance hall	4-17-13	Ok
Loc 17 in stairwell	4-17-13	OK
Loc 14 dining area	4-17-13	OK
Loc 13 stairwell	4-17-13	OK

P/O Richardson, P/O Miles

James Richardson

Fire Compliance Officer/Asst Patrol Officer

6-5-13

Date

Chief of Police

Lawrence W. Richards

Lawrence W. Richards

Date



Cheyney State University of Pennsylvania
Cheyney University Police Department – Fire Safety Division

ACADEMIC/ADMISTRATIVE BUILDING FIRE EXTINGUISHER REPORT

Building: ADA GEORGE DINING HALL

Date/Time of Inspection: June 5, 2013 0940hrs

Date/Time of Inspection:	Date of Last Inspection	Comments
Fire Extinguisher Number		
#1 at entrance	missing	missing
#7 near freezer	5-6-13	OK
#11 near 205	5-6-13	OK
#8 kitchen/sink	5-6-13	OK
#7 loc 12 exit in kit	5-6-13	OK
#5 near elevator	5-6-13	OK
#6 loc 14	5-6-13	OK
#9 in kitchen	5-6-13	OK
1-1 lower level exit	5-6-13	Recharge
1-2	5-6-13	OK
1-3 at stairwell	5-6-13	OK
1-5 in stairwell	5-6-13	Recharge
loc #6 in basement	5-6-13	OK
loc #3 basement	5-6-13	OK
1-1 near roll up door	moved	moved
1-2 in storeroom	moved	moved
1-3 inside dance hall	5-6-13	OK
1-4 in stairwell	5-6-13	OK
Loc 16 " dance hall	5-6-13	Ok
Loc 17 in stairwell	5-6-13	OK
Loc 14 dining area	5-6-13	OK
Loc 13 stairwell	5-6-13	OK

P/O Richardson, P/O Miles

Dolores Richardson

Fire Compliance Officer/Asst Patrol Officer

J. Richard

Chief of Police

6-5-13

Date

7-8-13

Date



Cheyney State University of Pennsylvania
Cheyney University Police Department - Fire Safety Division

ACADEMIC/ADMISTRATIVE BUILDING FIRE EXTINGUISHER REPORT

2.13.13-ok
near ROOM 118 ok
6-6-13

Building: ADA GEORGE DINING HALL

Date/Time of Inspection: ^{7/29/2013} December 5, 2012 0850 hrs @ 21:15 - 21:45

Fire Extinguisher Number	Date of Last Inspection	Comments
#1 at entrance	6.5.13	OK 77
#7 near freezer	6.5.13	OK 77
#11 near 205	?-2011	OK 77 needs tag
#8 kitchen/sink	3.4.13	OK 77
#7 loc 12 exit in kit	6.5.13	OK 77
#5 near elevator	6.5.13	OK 77
#6 loc 14	5.5.13	OK 77
#9 in kitchen	6.5.13	OK 77
1-1 lower level exit	missing	77
1-2	missing	77
1-3 at stairwell	6.5.13	OK 77
1-5 in stairwell	6.5.13	OK 77
loc #6 in basement	unknown	missing 77
loc #3 basement	6.5.13	OK 77
1-1 near roll up door	wrk	missing 77
1-2 in storeroom	2.13.13	OK 77
1-3 inside dance hall	missing	77
1-4 in stairwell	6.5.13	OK 77
Loc 16 " dance hall	6.5.13	OK 77
Loc 17 in stairwell	6.5.13	OK 77
Loc 14 dining area	6.5.13	OK 77
Loc 13 stairwell	6.5.13	OK 77

P/O Richardson - C. Wilson

Fire Compliance Officer/Asst Patrol Officer

Chief of Police

[Signature]

7-29-13

Date

Date

9413



Cheyenne State University of Pennsylvania
Cheyenne University Police Department – Fire Safety Division

ACADEMIC/ADMISTRATIVE BUILDING FIRE EXTINGUISHER REPORT

Building: ADA GEORGE DINING HALL

Date/Time of Inspection: 8/29/13 July 2013

Date/Time of Inspection:	Date of Last Inspection	Comments
Fire Extinguisher Number		
#1 at entrance		
#7 near freezer	8/29/13	
#11 near 205		
#8 kitchen/sink	8/29/13	
#7 loc 12 exit in kit		
#5 near elevator	8/29/13	
#6 loc 14		
#9 in kitchen		
1-1 lower level exit		
1-2		
1-3 at stairwell	8/29/13	OK
1-5 in stairwell	8/29/13	
loc #6 in basement		
loc #3 basement		
1-1 near roll up door	8/29/13	
1-2 in storeroom	8/29/13	
1-3 inside dance hall		
1-4 in stairwell	8/29/13	
Loc 16 " dance hall	8/29/13	
Loc 17 in stairwell	8/29/13	
Loc 14 dining area	8/29/13	
Loc 13 stairwell	8/29/13	
3 in storage 1-2	8/29/13	

[Signature]
Fire Compliance Officer/Asst. Patrol Officer

[Signature]
Lawrence W. Richards
Chief of Police

8/29/13
Date

9/16/13
Date

Transformer
mech 118

→ |



Cheyney State University of Pennsylvania
Cheyney University Police Department – Fire Safety Division

ACADEMIC/ADMISTRATIVE BUILDING FIRE EXTINGUISHER REPORT

Building: ADA GEORGE DINING HALL

Date/Time of Inspection: 9/30/13

Date/Time of Inspection:	Date of Last Inspection	Comments
Fire Extinguisher Number		
#1 at entrance	Aug 29 2013	CHARGE FULL
#7 near freezer	8/29/13	"
#11 near 205	↓	"
#8 kitchen/sink		"
#7 loc 12 exit in kit		"
#5 near elevator		"
#6 loc 14		"
#9 in kitchen		"
1-1 lower level exit		"
1-2		"
1-3 at stairwell		"
1-5 in stairwell		"
loc #6 in basement		"
loc #3 basement		"
1-1 near roll up door		"
1-2 in storeroom		"
1-3 inside dance hall		"
1-4 in stairwell		"
Loc 16 " dance hall		"
Loc 17 in stairwell		"
Loc 14 dining area		"
Loc 13 stairwell		8/29/13

[Signature]
Fire Compliance Officer/Asst Patrol Officer

9/30/13
Date

[Signature]
Lawrence W. Richards
Chief of Police

10/16/13
Date