



Cheyney State University of Pennsylvania  
Cheyney University Police Department – Fire Safety Division

**ACADEMIC/ADMISTRATIVE BUILDING FIRE EXTINGUISHER REPORT**

Building: KING HALL

Date/Time of Inspection: January 02, 2013 0902hrs

Fire Extingulsher Number		Date of Last Inspection	Comments	
B-1	at exit	12-4-12	Loc 23	OK
B-2	in corridor	10-4-12	Loc 24	OK
B-3	near rm 11	10-4-12	Loc 26	OK
B-4	at exit	10-4-12	Loc 25	tag required
1-1	in tv lounge	10-4-12	Loc 19	OK
1-2	near rm 118	10-4-12	Loc 21	OK
1-3	" 130	10-4-12	Loc 22	OK
2-1	" 226	10-4-12	Loc 18	OK
2-2	" 211	10-4-12	Loc 17	OK
2-3	" 201	10-4-12	Loc 16	OK
3-1	" 326	10-4-12	Loc 13	OK
3-2	" 311	10-4-12	Loc 14	OK
3-3	" 302	10-4-12	Loc 15	OK
4-1	" 426	10-4-12	Loc 12	OK
4-2	" 411	10-4-12	Loc 11	OK
4-3	" 402	10-4-12	Loc 10	OK
5-1	" 526	10-4-12	Loc 07	OK
5-2	" 511	10-4-12	Loc 08	OK
5-3	" 502	10-4-12	Loc 09	OK
6-1	" 626	10-4-12	Loc 06	OK
6-2	" 611	10-4-12		Missing
6-3	" 602	10-4-12	Loc 04	OK
1-4	In kitchen	10-4-12	Loc 14	OK

P/O Johnson

*P/O Aly Johnson #53*  
\_\_\_\_\_  
Fire Compliance Officer/Asst Patrol Officer

1-2-13  
\_\_\_\_\_  
Date

*Steve Richards*  
\_\_\_\_\_  
Chief of Police

1-2-13  
\_\_\_\_\_  
Date





Cheyney State University of Pennsylvania  
Cheyney University Police Department – Fire Safety Division

**ACADEMIC/ADMISTRATIVE BUILDING FIRE EXTINGUISHER REPORT**

Building: KING HALL

Date/Time of Inspection: 2-2-2013

Fire Extinguisher Number	Date of Last Inspection	Comments
B-1 at exit	JANUARY 2013	LOC -23 OK
B-2 in corridor	"	LOC-24 OK
B-3 near rm 11	"	LOC-26 OK
B-4 at exit	"	LOC-25 tag required
1-1 in tv lounge	"	LOC-19 OK
1-2 near rm 118	"	LOC-21 OK
1-3 " 130	"	LOC-22 OK
2-1 " 226	"	LOC-18 OK
2-2 " 211	"	LOC-17 OK
2-3 " 201	"	LOC-16 OK
3-1 " 326	"	LOC-13 OK
3-2 " 311	"	LOC-14 OK
3-3 " 302	"	LOC-15 OK
4-1 " 426	"	LOC-12 OK
4-2 " 411	"	LOC-11 OK
4-3 " 402	"	LOC-10 OK
5-1 " 526	"	LOC-07 OK
5-2 " 511	"	LOC-08 OK
5-3 " 502	"	LOC-09 OK
6-1 " 626	"	LOC-06 OK
6-2 " 611	"	MISSING
6-3 " 602	"	LOC-04 OK
1-4 in kitchen	"	LOC-14 OK

OFC Johnson  
Fire Compliance Officer/Asst Patrol Officer

[Signature]  
Chief of Police

2/2/13  
Date

2/28/13  
Date





Cheyney State University of Pennsylvania  
Cheyney University Police Department – Fire Safety Division

ACADEMIC/ADMISTRATIVE BUILDING FIRE EXTINGUISHER REPORT

Building: KING HALL

Date/Time of Inspection: March 6, 2013 0845 hrs

Fire Extinguisher Number	Date of Last Inspection	Comments
B-1 at exit		Loc 23 OK
B-2 in corridor		Loc 24 OK
B-3 near rm 11		Loc 26 OK
B-4 at exit		Loc 25 OK
1-1 in tv lounge		Loc 19 OK
1-2 near rm 118		Loc 21 OK
1-3 " 130		Loc 22 OK
2-1 " 226		Loc 18 OK
2-2 " 211		Loc 17 OK
2-3 " 201		Loc 16 OK
3-1 " 326		Loc 13 OK
3-2 " 311		Loc 14 OK
3-3 " 302		Loc 15 OK
4-1 " 426		Loc 12 OK
4-2 " 411		Loc 11 OK
4-3 " 402		Loc 10 OK
5-1 " 526		Loc 07 OK
5-2 " 511		Loc 08 OK
5-3 " 502		Loc 09 OK
6-1 " 626		Loc 06 OK
6-2 " 611		OK
6-3 " 602		Loc 04 OK
1-4 In kitchen		Loc 14 OK

P/O Richardson/Miles

Fire Compliance Officer/Asst Patrol Officer

3.6.13

Date

Chief of Police

Date





Cheyney State University of Pennsylvania  
Cheyney University Police Department – Fire Safety Division

ACADEMIC/ADMISTRATIVE BUILDING FIRE EXTINGUISHER REPORT

Building: KING HALL

Date/Time of Inspection: 4-6-2013 1500 hours

Fire Extinguisher Number	Date of Last Inspection	Comments
B-1 at exit	March 5, 2013	LOC-23 OK
B-2 in corridor	"	LOC-24 OK
B-3 near rm 11	"	LOC-26 OK
B-4 at exit	"	LOC-25 tag required
1-1 in tv lounge	"	LOC-19 OK
1-2 near rm 118	"	LOC-21 OK
1-3 " 130	"	LOC-22 OK
2-1 " 226	"	LOC-18 OK
2-2 " 211	"	LOC-17 OK
2-3 " 201	"	LOC-16 OK
3-1 " 326	"	LOC-13 OK
3-2 " 311	"	LOC-14 OK
3-3 " 302	"	LOC-15 OK
4-1 " 426	"	LOC-12 OK
4-2 " 411	"	LOC-11 OK
4-3 " 402	"	LOC-10 OK
5-1 " 526	"	LOC-07 OK
5-2 " 511	"	LOC-08 OK
5-3 " 502	"	LOC-09 OK
6-1 " 626	"	LOC-06 OK
6-2 " 611	"	MISSING
6-3 " 602	"	LOC-04 OK
1-4 in kitchen	"	LOC-14 OK

D. Johnson # 53  
Fire Compliance Officer/Asst Patrol Officer

4-6-13  
Date

\_\_\_\_\_  
Chief of Police

\_\_\_\_\_  
Date







Cheyney State University of Pennsylvania  
Cheyney University Police Department – Fire Safety Division

**ACADEMIC/ADMISTRATIVE BUILDING FIRE EXTINGUISHER REPORT**

Building: KING HALL

Date/Time of Inspection: May 3, 2013 1100 hrs

Fire Extinguisher Number		Date of Last Inspection	Comments	
B-1	at exit	4-6-13	Loc 23	OK
B-2	in corridor	"	Loc 24	OK
B-3	near rm 11	"	Loc 26	OK
B-4	at exit	"	Loc 25	OK
1-1	in tv lounge	"	Loc 19	OK
1-2	near rm 118	"	Loc 21	OK
1-3	" 130	"	Loc 22	OK
2-1	" 226	"	Loc 18	OK
2-2	" 211	"	Loc 17	OK
2-3	" 201	"	Loc 16	OK
3-1	" 326	"	Loc 13	OK
3-2	" 311	"	Loc 14	Recharge/Tag
3-3	" 302	"	Loc 15	OK
4-1	" 426	"	Loc 12	OK
4-2	" 411	"	Loc 11	Tag required
4-3	" 402	"	Loc 10	OK
5-1	" 526	"	Loc 07	OK
5-2	" 511	"	Loc 08	Tag required
5-3	" 502	"	Loc 09	OK
6-1	" 626	"	Loc 06	OK
6-2	" 611	"		OK
6-3	" 602	"	Loc 04	OK
1-4	In kitchen	"	Loc 14	OK

P/O Wilson

\_\_\_\_\_  
Fire Compliance Officer/Asst Patrol Officer

\_\_\_\_\_  
Date

\_\_\_\_\_  
Chief of Police

\_\_\_\_\_  
Date





Cheyney State University of Pennsylvania  
Cheyney University Police Department – Fire Safety Division

**ACADEMIC/ADMISTRATIVE BUILDING FIRE EXTINGUISHER REPORT**

Building: KING HALL

Date/Time of Inspection: June 3, 2013 0830 hrs

Fire Extinguisher Number		Date of Last Inspection	Comments	
B-1	at exit	5-6-13	Loc 23	OK
B-2	in corridor	"	Loc 24	OK
B-3	near rm 11	"	Loc 26	OK
B-4	at exit	"	Loc 25	OK
1-1	in tv lounge	"	Loc 19	OK
1-2	near rm 118	"	Loc 21	OK
1-3	" 130	"	Loc 22	OK
2-1	" 226	"	Loc 18	OK
2-2	" 211	"	Loc 17	OK
2-3	" 201	"	Loc 16	OK
3-1	" 326	"	Loc 13	OK
3-2	" 311	"	Loc 14	Recharge/Tag
3-3	" 302	"	Loc 15	OK
4-1	" 426	"	Loc 12	OK
4-2	" 411	"	Loc 11	Recharge
4-3	" 402	"	Loc 10	OK
5-1	" 526	"	Loc 07	OK
5-2	" 511	"	Loc 08	Recharge
5-3	" 502	"	Loc 09	OK
6-1	" 626	"	Loc 06	OK
6-2	" 611	"		OK
6-3	" 602	"	Loc 04	OK
1-4	In kitchen	"	Loc 14	OK

P/O Richardson/Miles

*Dolores Richardson*

Fire Compliance Officer/Asst Patrol Officer

*J. W. Richard*

Chief of Police

6-3-13

Date

7-8-13

Date





Cheyney State University of Pennsylvania  
Cheyney University Police Department – Fire Safety Division

**ACADEMIC/ADMISTRATIVE BUILDING FIRE EXTINGUISHER REPORT**

Building: KING HALL

Date/Time of Inspection: 7/17/2013 1155 hours

Fire Extinguisher Number	Date of Last Inspection	Comments
B-1 at exit	June 3, 2013	LOC-23 OK
B-2 in corridor	"	LOC-24 OK
B-3 near rm 11	"	LOC-26 OK
B-4 at exit	"	LOC-25 No tag
1-1 in tv lounge	"	LOC-19 OK
1-2 near rm 118	"	LOC-21 OK
1-3 " 130	"	LOC-22 OK
2-1 " 226	"	LOC-18 OK
2-2 " 211	"	LOC-17 OK
2-3 " 201	"	LOC-16 OK
3-1 " 326	"	LOC-13 OK
3-2 " 311	"	LOC-14 No tag- needs recharge
3-3 " 302	"	LOC-15 OK
4-1 " 426	"	LOC-12 OK
4-2 " 411	"	LOC-11 Needs recharge
4-3 " 402	"	LOC-10 OK
5-1 " 526	"	LOC-07 OK
5-2 " 511	"	LOC-08 Needs recharge
5-3 " 502	"	LOC-09 OK
6-1 " 626	"	LOC-06 OK
6-2 " 611	"	MISSING
6-3 " 602	"	LOC-04 OK
1-4 in kitchen	"	LOC-14 OK

P/O Johnson #53  
Fire Compliance Officer/Asst Patrol Officer

[Signature]  
Chief of Police

7/17/13  
Date

9-4-13  
Date





Cheyney State University of Pennsylvania  
Cheyney University Police Department – Fire Safety Division

ACADEMIC/ADMISTRATIVE BUILDING FIRE EXTINGUISHER REPORT

Building: KING HALL

Date/Time of Inspection: August 23, 2013

Fire Extinguisher Number	Date of Last Inspection	Comments
B-1 at exit	July 17, 2013	Loc 23 GOOD
B-2 in corridor	July 17, 2013	Loc 24 GOOD
B-3 near rm 11	July 17, 2013	Loc 26
B-4 at exit	July 17, 2013	Loc 25 NO CASE
1-1 in tv lounge	June 3, 2013	Loc 19
1-2 near rm 118	July " 17, 2013	Loc 21 GOOD
1-3 " 130	July " 17, 2013	Loc 22 GOOD
2-1 " 226	July " 17, 2013	Loc 18 N/CASE
2-2 " 211	July " 17, 2013	Loc 17 <del>N/CASE</del> N/CASE
2-3 " 201	July " 17, 2013	Loc 16 GOOD
3-1 " 326	July " 17, 2013	Loc 13 NO GLASS
3-2 " 311	May 3, 2013	Loc 14 NO GLASS
3-3 " 302	May 3, 2013	Loc 15 Crack glass
4-1 " 426	Dec " 2012	Loc 12
4-2 " 411	Dec 1, 2012	Loc 11 NO GLASS
4-3 " 402	July 17, 2013	Loc 10 GOOD
5-1 " 526	" "	Loc 07
5-2 " 511	Feb " 2013	Loc 08 NO GLASS
5-3 " 502	May 3, 2013	Loc 09
6-1 " 626	May 3, 2013	Loc 06
6-2 " 611	May 22, 2013	NO GLASS
6-3 " 602	June " 3, 2013	Loc 04
1-4 In kitchen	June " 3, 2013	Loc 14

Hellen E. Lanza  
Fire Compliance Officer/Asst Patrol Officer

August 23, 2013  
Date

Lewrence W. Richards  
Chief of Police

9/16/13  
Date







Cheyney State University of Pennsylvania  
Cheyney University Police Department – Fire Safety Division

**ACADEMIC/ADMISTRATIVE BUILDING FIRE EXTINGUISHER REPORT**

Building: KING HALL

Date/Time of Inspection: 9-12-13

Fire Extinguisher Number		Date of Last Inspection	Comments
B-1	at exit	8-12-13	Loc 23 GOOD
B-2	in corridor	8-12-13	Loc 24 GOOD
B-3	near rm 11	8-12-13	Loc 26 GOOD
B5- B-4	at exit	8-12-13	Loc 25 GOOD
1-1	in tv lounge	8-12-13	Loc 19 GOOD
1-2	near rm 118	8-12-13	Loc 21 GOOD
1-3	" 130	8-12-13	Loc 22 GOOD
2-1	" 226	8-12-13	Loc 18 NO GLASS
2-2	" 211	8-12-13	Loc 17 NO GLASS
2-3	" 201	8-12-13	Loc 16 GOOD
3-1	" 326	8-12-13	Loc 13 NO GLASS
3-2	" 311	8-12-13	Loc 14 NO GLASS
3-3	" 302	8-12-13	Loc 15 Glass crack
4-1	" 426	8-12-13	Loc 12 GOOD
4-2	" 411	8-12-13	Loc 11 NO GLASS FN BOX
4-3	" 402	8-12-13	Loc 10 GOOD
5-1	" 526	8-12-13	Loc 07 GOOD
5-2	" 511	8-12-13	Loc 08 NO GLASS
5-3	" 502	9-12-13	Loc 09 GOOD
6-1	" 626	8-12-13	Loc 06 GOOD
6-2	" 611	8-12-13	NO CASE GLASS MISSING
6-3	" 602	8-12-13	Loc 04 GOOD
1-4	In kitchen	8-12-13	Loc 14 GOOD

Fire Compliance Officer/Asst Patrol Officer

Date Sept 12, 2013

Lawrence W. Richards

